



Most Common Service Questions about the AH-2, AH-3 and AT-120

The information on this page is subject to the [terms and conditions set forth on the ICOM America Service FAQ Index page.](#)

Symptom: Won't start tuning.

Probable Cause: Faulty regulator.

Cure: Replace faulty IC9 8-volt regulator.

Symptom: Won't start tuning.

Probable Cause: Start line goes low, but key line remains high.

Cure: Replace faulty Q2, Q3, or Q4 transistors.

Symptom: Won't tune on some bands.

Probable Cause: Faulty IC10, IC11, or IC12.

Cure: Replace faulty ICs.

Remarks: Check resistor-cap pairs next to relays for signs of overheating.

Symptom: In AH2 controller: "TUNE" and "THRU" LEDs don't work.

Probable Cause: Faulty IC1 and/or IC2 5-volt regulator.

Cure: Replace defective parts.

[FAQ Index Page](#) | [Amateur Radios](#)

[ICOM Homepage](#) [Dealers](#) [New Radios](#) [Calendar](#) [Specials](#) [Get In Touch With ICOM](#)

©1997 ICOM America, Inc. The ICOM logo is a registered trademark of ICOM, Inc. All ICOM radios significantly exceed FCC regulations limiting spurious emissions. All stated specifications are subject to change without notice or obligation.