


INSTRUCTION MANUAL ADDENDUM

PUBLICATION NO.: PM — 0700	DATE OF ISSUE: 20 September 1968
MODEL: RF-301	CHANGES EFFECTIVE: 2694-2723 only

The above listed RF-301 SSB Transceivers have been modified to provide an external keyline output signal (ground in transmit) and a external operate mode (+12 vdc for all operate modes of the RF-301) signal. The modification consists of the addition of a terminal board to the rear panel of the unit, above REMOTE connector J3, an added capacitor, and interconnecting wiring. The diagram below shows the modification schematically.



RF COMMUNICATIONS, INC. - ROCHESTER, NEW YORK, U. S. A.

INSTRUCTION MANUAL ADDENDUM

OK

PUBLICATION NO.: PM — 0594(E)	DATE OF ISSUE: 8 August 1968
MODEL: RF 301/A/E	CHANGES EFFECTIVE: S/N 2664

The following changes have been made to the RF 301, RF 301A and RF 301E SSB Transceivers. Change your instruction manuals as follows:

Change Parts List as follows:

Page 7-5, Divider/Spectrum Generator---Add C48, Capacitor, dipped mica, 510 uF, 500 VDCW, 5%; RF P/N C-0145 ✓

Page 7-8, Translator---Add C31, Capacitor, tantalum, 15 uF, 20 VDCW; RF P/N C-5832 ✓

Change Circuit Diagrams as follows:

Page 8-5/8-6, Figure 8.4---Show added capacitor C48, 510 uF, connected between Q13 collector (positive) and ground ✓

Page 8-11/8-12, Figure 8.10---Show added capacitor C31, 15 uF, connected between the tie point of R17, CR16, and T1 (positive) and ground. ✓

RF COMMUNICATIONS, INC. - ROCHESTER, NEW YORK, U. S. A.

oh.

INSTRUCTION MANUAL ADDENDUM

PUBLICATION NO.: PM — 0590 (E)	DATE OF ISSUE: 10 July 1968
MODEL: RF-301/A/P	CHANGES EFFECTIVE:

Inductor L2 on the 162-1000 board, Megacycle Oscillator Assembly, has been changed to 1000 uH. Make the following corrections to your instruction manual.

Change Megacycle Oscillator Parts Lists as follows:

For RF-301 (PM-0301C) and RF-301A (PM-0348C)

Page 7-11--- L2 is now 1000 uH; RF P/N L-0050 ✓

For RF-301P (PM-0540)

Page 7-9--- L2 is now 1000 uH; RF P/N L-0050

Change Circuit Diagrams as follows:

For RF-301 (PM-0301C) and RF-301A (PM-0348C)

Page 8-19/8-20, figure 8.18--- L2 is now 1000 uH ✓

For RF-301P (PM-0540)

Page 8-19/8-20, figure 8.9--- L2 is now 1000 uH

RF COMMUNICATIONS, INC. - ROCHESTER, NEW YORK, U. S. A.

OK.

INSTRUCTION MANUAL ADDENDUM

PUBLICATION NO.: PM — 0587(E) Page 1	DATE OF ISSUE: 21 June 1968
MODEL: RF-301/A/P	CHANGES EFFECTIVE: See below

Effectivity: On all 162-0300 assemblies manufactured after 6-21-68 and as required to correct assemblies in test.

The following changes have been made to the 162-0300 Divider/Spectrum Generator assembly manufactured after 21 June 1968. Transistors Q5 and Q9 have been changed from type 2N1301 (RF P/N Q-0109) to type 2N3638A (RF P/N Q-0319). The change to the 2N3638A transistor was made to reduce variations in the 100 Kc and 10 Kc pulse widths due to variations in individual transistors. Make the following changes in your instruction manual.

A. FOR RF-301 (PM-0301E) AND RF-301A (PM-0348E)

Change text as follows:

Page 6-20, figure 6.12--Change pulse width to 0.9 ± 0.15 u sec measured at the 90% amplitude point.

Page 6-21, figure 6.16--Change pulse width to 8.5 ± 1.5 usec measured at the 90% amplitude point.

Page 6-22, figure 6.20--Change pulse width to 38 ± 6 usec measured at the 90% amplitude point. ✓

Change Parts Lists as follows:

Page 7-5--Q5 is now type 2N3638A; RF P/N Q-0319.
Q9 is now type 2N3638A; RF P/N Q-0319. ✓

Change Circuit Diagrams as follows:

Page 8-5/8-6, figure 8.4--Q5 and Q9 are now type 2N3638A. Add note 2 as follows--"2. Q5 and Q9 should be replaced only by type 2N3638A." Add "NOTE 2" to Q5 and Q9. ✓

RF COMMUNICATIONS, INC. - ROCHESTER, NEW YORK, U. S. A.

INSTRUCTION MANUAL ADDENDUM

PUBLICATION NO.: PM— 0587(E) Page 2	DATE OF ISSUE: 21 June 1968
MODEL: RF-301/A/P	CHANGES EFFECTIVE: See page 1

B. FOR RF-301P (PM-0540)

Change text as follows:

Page 6-21, figure 6.10--Change pulse width to 0.9 ± 0.15 used measured at the 90% amplitude point.

Page 6-22, figure 6.14--Change pulse width of 8.5 ± 1.5 usec measured at the 90% amplitude point.

Page 6-23, figure 6.18--Add pulse width of 38 ± 6 usec measured at the 90% amplitude point.

Change Parts List as follows:

Page 7-1, Divider/Spectrum Generator--Q5 is now type 2N3638A; RF P/N Q-0319. Q9 is now type 2N3638A; RF P/N Q-0319.

Change Circuit Diagrams as follows:

Page 8-5/8-6, figure 8.2--Q5 and Q9 are now type 2N3638A. Add note 2 as follows--"2. Q5 and Q9 should be replaced only by type 2N3638A." Add "NOTE 2" to Q5 and Q9.

RF COMMUNICATIONS, INC. - ROCHESTER, NEW YORK, U. S. A.

A

INSTRUCTION MANUAL ADDENDUM

PUBLICATION NO.: PM — 0581 (E)	DATE OF ISSUE: 14 June 1968
MODEL: RF-301/A	CHANGES EFFECTIVE: S/N 2582

Capacitor C2 on ACC assembly, 162-1600, has been removed from the emitter circuit of Q2 and reconnected between ground and the collector of Q2. The value of C2 is now 15 uF at 20 volts. Make the following changes in your instruction manual.

Change Parts List as follows:

Page 7-13 (ACC Circuit)--C2 is now 15 uF, 20 VDCW, RF P/N C-5832. ✓

Change Circuit Diagrams as follows:

Figure 8.28--Show C2 removed from the emitter of Q2 and reconnected between ground, negative lead, and the collector of Q2, positive lead. Change the value of C2 to 15 uF, 20 v. ✓

RF COMMUNICATIONS, INC. - ROCHESTER, NEW YORK, U. S. A.

OK

INSTRUCTION MANUAL ADDENDUM

PUBLICATION NO.: PM — 0580 (E)	DATE OF ISSUE: 6 June 1968
MODEL: RF 301/A	CHANGES EFFECTIVE: See below

Make the following corrections to instruction manual PM-0301E or to PM-0348E.

Change parts list as follows:

Page 7-3--Add CR4; diode, silicon, 1N4001, RF P/N CR-0043 ✓

Change circuit diagrams as follows:

Page 8-3--Change diode CR3, connected between terminals 13 and 14 of relay K1 to CR4. ✓

RF COMMUNICATIONS, INC. - ROCHESTER, NEW YORK, U. S. A.

oh

INSTRUCTION MANUAL ADDENDUM

PUBLICATION NO.: PM — 0579(E)	DATE OF ISSUE: 6 June 1968
MODEL: RF 301/A/P	CHANGES EFFECTIVE:

Transformer T7 on the 162-0800 assembly has been changed. Make the following corrections to the parts list in your instruction manual.

RF 301/RF 301A

Page 7-11--T7 is now 162-0166 ✓

RF-301P

Page 7-8--T7 is now 162-0166

RF COMMUNICATIONS, INC. - ROCHESTER, NEW YORK, U. S. A.

ok.

INSTRUCTION MANUAL ADDENDUM

PUBLICATION NO.: PM— 0574 (D, E)	DATE OF ISSUE: 18 April 1968
MODEL: RF-301/A/E	CHANGES EFFECTIVE: See below

Per SDN No. 8-108-1 effective on serial numbers: 1670-1674, 1817, 2020-2029, 2038-2069 and 2380 and above

Capacitor C60, located on the RF Amplifier and connected between terminal 7 and ground on relay K1, has been changed to 82 pF. Make the following corrections in your instruction manual to show the new value.

Change Parts List as follows:

Page 7-3---C60 is now 82 pF; RF P/N C-0124 ✓

Change Circuit Diagrams as follows:

Figure 8.2---C60 is now 82 pF. ✓

RF COMMUNICATIONS, INC. - ROCHESTER, NEW YORK, U. S. A.

A

INSTRUCTION MANUAL ADDENDUM

PUBLICATION NO.: PM — 0560 (D)	DATE OF ISSUE: 8 March 1968
MODEL: RF-301	CHANGES EFFECTIVE: See below

Serial number _____

On the RF-301 SSB Transceiver with the above listed serial number the following changes have been made to the main frame circuitry. In the high voltage section of the power supply a 100 ohm, 5 watt resistor, R17, has been added in parallel with choke L4-B. Capacitor C10, located in the +12 vdc filter, has been increased to 580 uF.

Change your instruction manual as outlined below to show the added resistor and changed capacitor.

Change Parts List as follows:

Page 7-1--Change C10 to--Capacitor, electrolytic, 580 uF, 15 VDCW; ✓
RF P/N C-4162

Page 7-2--Add R17, Resistor, wirewound, 100 ohms, 5 watts, ±10%; ✓
RF P/N R-3814

Change Circuit Diagrams as follows:

Page 8-33/8-34--Figure 8.31--Show added resistor, R17, 100 ohms, 5 watts, connected across L4-B. Show capacitor C10 as 580 uF, 15 V. ✓

RF COMMUNICATIONS, INC. - ROCHESTER, NEW YORK, U. S. A.

011. 7/12-70

INSTRUCTION MANUAL ADDENDUM

PUBLICATION NO.: PM— 0541	DATE OF ISSUE: 1 February 68
MODEL: RF-301	CHANGES EFFECTIVE: See below

Serial No. _____

For the above listed serial number RF-301 SSB Transceiver change Instruction Manual PM-0301D as follows:

Parts List

Page 7-13--ALC Circuit Assembly---C2 is 20% RF P/N C-2350 ✓

RF COMMUNICATIONS, INC. - ROCHESTER, NEW YORK, U. S. A.



RF COMMUNICATIONS, INC.
1680 UNIVERSITY AVENUE
ROCHESTER, NEW YORK, 14610, U.S.A.

INSTRUCTION MANUAL ADDENDUM

ADDENDUM No. PM-0953

APPLICABLE TO: RF-301/A

APPLICABLE SDN No.(S) LPES-54

(162-0200 Assembly)

APPLICABLE DCN No.(S)

The gain of V1 has been changed to reduce the plate dissipation and increase the gain. Make the following changes in your instruction manual PM-0301F or PM-0348E.

NOTE

For PM-0348E make the changes outlined below for page 7-3 on page 7-4.

Page 7-3, Parts List, RF Amplifier Assembly.....

R10 is now--82 ohms, 5W, 5%	RF P/N	R-3231
R11 is now--8.2 K, 5W, 5%	RF P/N	R-3232
R12 is now--4.7K, 2W, 5%	RF P/N	R-3233
R13 is now--4.7K, 2W, 5%	RF P/N	R-3233

Page 8-3/8-4, Circuit Diagram, Figure 8.2.....

Change: R10 to 82 ohms at 5W
R11 to 8.2K
R12 to 4.7K
R13 to 4.7K at 2W



RF COMMUNICATIONS, INC.
1680 UNIVERSITY AVENUE
ROCHESTER, NEW YORK, 14610, U.S.A.

INSTRUCTION MANUAL ADDENDUM

ADDENDUM No. PM-0957

APPLICABLE TO: RF-301/A
(162-1500 Assembly)

APPLICABLE SDN No.(S) LPES-58

APPLICABLE DCN No.(S)

Make the following changes in your Instruction Manual
PM-0301F, PM-0301G, or PM-0348E, PM-0348G.

Pg. 7-12, Parts List, 162-1500.....

Delete: R4

Change: R3 to 18K RF P/N R-0039

Pg. 8-27/8-28, figure 8.26, Schematic Diagram 162-1500.....

Delete: R4

Change: R3 to 18K



RF COMMUNICATIONS, INC.
1680 UNIVERSITY AVENUE
ROCHESTER, NEW YORK, 14610, U.S.A.

INSTRUCTION MANUAL ADDENDUM

ADDENDUM No. PM-0958

APPLICABLE TO: RF-301/A

APPLICABLE SDN No.(S) LPES-60

(162-0800)

APPLICABLE DCN No.(S)

Make the following changes in your Instruction
Manual PM-0301G or PM-0348G.

Pg. 7-10, Parts List, 162-0800.....

Change: R47 to 33 ohms $\pm 5\%$; 1W RF P/N R-1613.

Pg. 8/15/8-16, Schematic Diagram, 162-0800.....

Change: R47 to 33 ohms.



RF COMMUNICATIONS, INC.
1680 UNIVERSITY AVENUE
ROCHESTER, NEW YORK, 14610, U.S.A.

INSTRUCTION MANUAL ADDENDUM

ADDENDUM No. PM-0960

APPLICABLE SDN No.(S) LPES-62

APPLICABLE DCN No.(S)

APPLICABLE TO: RF-301/A
(162-0500 Assembly)

Make the following changes to your Instruction Manual
PM-0301F, PM-0301G, or PM-0348E, PM-0348G.


Pg. 7-6, Parts List, 162-0500.....

Add: C38, Capacitor; .005uF; 500Vdcw RF P/N C-0002.

Pg. 8-9/8-10, Schematic Diagram, 162-0500.....

Add: C38 .005uF

Show C38 added at the junction of R12 and R30 as
shown below:





RF COMMUNICATIONS, INC.
1680 UNIVERSITY AVENUE
ROCHESTER, NEW YORK, 14610, U.S.A.

INSTRUCTION MANUAL ADDENDUM

ADDENDUM No. PM-0963

APPLICABLE TO: RF-301/A
(162-0500 Assembly)

APPLICABLE SDN No.(S)

APPLICABLE DCN No.(S) LPE-210

Make the following changes in your Instruction Manual
PM-0301G or PM-0348G.

Page 7-6, Patrs List, 162-0500.....

Change: FL3-C4 RF P/N to C-0108.



RF COMMUNICATIONS, INC.
1680 UNIVERSITY AVENUE
ROCHESTER, NEW YORK, 14610, U.S.A.

INSTRUCTION MANUAL ADDENDUM

ADDENDUM No. PM-0964

APPLICABLE TO: RF-301/A
(162-0040 Assembly)

APPLICABLE SDN No.(S)

APPLICABLE DCN No.(S) LPE-214

The following changes have been made in the Main Frame Assembly of the RF-301 SSB Transceiver. Make the corrections below to your Instruction Manual PM-0301G or PM-0348G.

Pg. 7-1, Parts List, Main Frame.....

Change: C31 RF P/N to C-0616.

CR12 to type UZ8709, RF P/N CR-0352.

Pg. 8-33/8-34, Schematic Diagram, Main Frame.....

Change: CR12 to UZ8709.



RF COMMUNICATIONS, INC.
1680 UNIVERSITY AVENUE
ROCHESTER, NEW YORK, 14610, U.S.A.

INSTRUCTION MANUAL ADDENDUM

ADDENDUM No. PM-0965A

APPLICABLE TO: RF-301/A

APPLICABLE SDN No.(S) LPES-59&66 , (162-0400 Assembly)

APPLICABLE DCN No.(S)

Make the following changes in your Instruction Manual
PM-0301G or PM-0348G.

Pg. 7-5/7-6, Parts List, 162-0400.....

Change: C7 to 68 pF RF P/N C-0122.
C32 to 100 pF RF P/N C-0126.
Q1 through Q4 and Q6 through Q9 to type
2N4916, RF P/N Q-0360.
R21 to 2.2K RF P/N R-0028.

Pg. 8-7/8-8, Figure 8.6, Schematic Diagram, 162-0400.....

Change: C7 to 68 pF.
C32 to 100 pF.
Q1 through Q4 and Q6 through Q9 to type 2N4916.
R21 to 2.2K.



RF COMMUNICATIONS, INC.
1680 UNIVERSITY AVENUE
ROCHESTER, NEW YORK, 14610, U.S.A.

INSTRUCTION MANUAL ADDENDUM

ADDENDUM No. PM-0968

APPLICABLE TO: RF-301/A
(162-0500 Assembly)

APPLICABLE SDN No.(S) LPES-64

APPLICABLE DCN No.(S)

Make the following changes in your Instruction Manual PM-0301G or PM-0348G.

Pg. 7-6, Parts List, 162-0500.....

Change: Q6 from 2N4916 to 2N2084 RF P/N Q-0105.

Pg. 8-9/8-10, Schematic Diagram, 162-0500.....

Change: Q6 to 2N2084



RF COMMUNICATIONS, INC.
1680 UNIVERSITY AVENUE
ROCHESTER, NEW YORK, 14610, U.S.A.

INSTRUCTION MANUAL ADDENDUM

ADDENDUM No. PM-0969

APPLICABLE TO: RF-301/A

APPLICABLE SDN No.(S)

(162-0500 Assembly)

APPLICABLE DCN No.(S)

Make the following changes in your Instruction Manual PM-0301G or PM-0348G.

Page 7-6, Parts List.....

Change: CR9 to type UZ709, RF P/N CR-0048.

Page 7-7, Parts List.....

Change: R40 to 56 ohms, RF P/N R-0209.

Page 8-9/8-10, Circuit Diagrams.....

Change: CR9 to UZ709 and R40 to 56 ohms.



RF COMMUNICATIONS, INC.
1680 UNIVERSITY AVENUE
ROCHESTER, NEW YORK, 14610, U.S.A.

INSTRUCTION MANUAL ADDENDUM

ADDENDUM No. PM-0970
APPLICABLE SDN No.(S) LPES-65
APPLICABLE DCN No.(S)

APPLICABLE TO: RF-301/A
(162-1200 Assembly)



Make the following changes in your Instruction Manual
PM-0301G or PM-0348G.

Pg. 7-11, Parts List.....

Add: Z1 Ferrite Bead, RF P/N E-0652.

Pg. 8-23/8-24, Schematic Diagram.....

Add: Z1 Ferrite Bead
Show Z1 added to base lead of Q1 as shown
below:





RF COMMUNICATIONS, INC.
1680 UNIVERSITY AVENUE
ROCHESTER, NEW YORK, 14610, U.S.A.

INSTRUCTION MANUAL ADDENDUM

ADDENDUM No. PM-0986

APPLICABLE SDN No.(S)

APPLICABLE DCN No.(S) LPE-242

APPLICABLE TO: RF-301/A
(162-0600 Assembly)

Make the following changes in your Instruction Manual
PM-0301G or PM-0348G.

Page 8-11/8-12, Schematic Diagram, 162-0600.....

Change Resistors R7 and R20 to 560 ohms 1/4 W.



RF COMMUNICATIONS, INC.
1680 UNIVERSITY AVENUE
ROCHESTER, NEW YORK, 14610, U.S.A.

INSTRUCTION MANUAL ADDENDUM

ADDENDUM No. PM-0987

APPLICABLE SDN No.(S)

APPLICABLE DCN No.(S) LPE-241

APPLICABLE TO: RF-301/A

(162-0400 Assembly)

Make the following changes in your Instruction Manual
PM-0301G or PM-0348G.

Page 7-5, Parts List, 162-0400.....

Change: C25 to 43 pF \pm 2% RF P/N C-2469
C9 to 110 pF RF P/N C-0127
CR1, CR2, CR3, and CR4 to Diode Type 1N4454
RF P/N CR-0705.

Page 8-7/8-8, Figure 8.6 Schematic Diagram, 162-0400.....

Change: C9 to 110 pF
C25 to 43 pF
CR1, CR2, CR3, and CR4 to 1N4454



RF COMMUNICATIONS, INC.
1680 UNIVERSITY AVENUE
ROCHESTER, NEW YORK, 14610, U.S.A.

INSTRUCTION MANUAL ADDENDUM

ADDENDUM No. PM-0988

APPLICABLE TO: RF-301/A
(Main Frame Assembly)

APPLICABLE SDN No.(S)

APPLICABLE DCN No.(S) LPE-240

Make the following changes in your Instruction Manual
PM-0301G or PM-0348G.

Page 7-2, Parts List, Main Frame.....

Change the RF Part Number of P7, P8, P12, P13, P16, P17,
P24, P33, P34, P35, P42, and P43, to P-0043.



RF COMMUNICATIONS, INC.
1680 UNIVERSITY AVENUE
ROCHESTER, NEW YORK, 14610, U.S.A.

INSTRUCTION MANUAL ADDENDUM

ADDENDUM No. PM-1070

APPLICABLE TO: RF-3011A
(162-0500 Assy.)

APPLICABLE SDN No.(S) 1086

APPLICABLE DCN No(S)

Make the following changes in your RF-301 Instruction Manual, PM-0301G or PM-0348G.

Parts List, page 7-6, 162-0500 Assembly

Change R40 to 68 ohms, RF P/N R-0210

Circuit Diagrams, page 8-9/8-10, figure 8.8

Change R40 to 68



RF COMMUNICATIONS, INC.
1680 UNIVERSITY AVENUE
ROCHESTER, NEW YORK, 14610, U.S.A.

INSTRUCTION MANUAL ADDENDUM

ADDENDUM No. PM-1071

APPLICABLE SDN No(S) 1087

APPLICABLE DCN No(S)

APPLICABLE TO RF-304 - 26.0 VDC
Power Module
(162-1800)

A 0.1 μ F capacitor has been added to the 162-1800 Assembly. Make the following additions to your RF-301 Instruction Manual (PM-0301G or PM-0348G) or to the RF-303/RF-304 Instruction Sheet PM-0709B.

Parts List, page 7-13, RF-304 Assembly

Add: Capacitor, ceramic, 0.1 μ F, 75 VDCW; RF P/N C-0063

Circuit Diagrams, page 8-37/8-38, figure 8.33

Show added capacitor (0.1 μ F) connected between collector of Q1 and terminal 2 of T1.



RF COMMUNICATIONS, INC.
1680 UNIVERSITY AVENUE
ROCHESTER, NEW YORK, 14610, U.S.A.

INSTRUCTION MANUAL ADDENDUM

ADDENDUM No. PM-0961

APPLICABLE TO: RF-301/A
(162-0901 Assembly)

APPLICABLE SDN No.(S)

APPLICABLE DCN No.(S) LPE-219

Make the following changes in your Instruction Manual
PM-0301G or PM-0348G.

Pg. 7-10, Parts List, 162-0901.....

Change: Q1 through Q4 to Transistor, type 2N4916
RF P/N Q-0360.

Pg. 8-17/8-18, Schematic Diagram, 162-0900.....

Change: Q1 through Q4 to 2N4916.



RF COMMUNICATIONS, INC.
1680 UNIVERSITY AVENUE
ROCHESTER, NEW YORK, 14610, U.S.A.

INSTRUCTION MANUAL ADDENDUM

ADDENDUM No. PM-0962

APPLICABLE TO: RF-301/A
(162-1600 Assembly)

APPLICABLE SDN No.(S)

APPLICABLE DCN No.(S) LPE-216

Make the following changes in your Instruction Manual PM-0301G or PM-0348G.

Pg. 7-12, Parts List, 162-1600 Assembly.....

Change: Q2 to Transistor, type 2N3565 RF P/N Q-0311.

R6 RF P/N to R-3361.

Pg. 8-29/8-30, figure 8.28, Schematic Diagram, 162-1600.....

Change: Q2 to 2N3565.



RF COMMUNICATIONS, INC.
1680 UNIVERSITY AVENUE
ROCHESTER, NEW YORK, 14610, U.S.A.

INSTRUCTION MANUAL ADDENDUM

ADDENDUM No. PM-0980A

APPLICABLE SDN No.(S)

APPLICABLE DCN No.(S) LPE-233

APPLICABLE TO: RF-301/A
(MAIN FRAME ASSEMBLY)

Make the following changes in your Instruction Manual PM-0301G or PM-0348G.

Page 7-1 and 7-2, Parts List, Main Frame Assembly.....

Change: C3 to Capacitor, Electrolytic, two section (C3-A) 5 μ F; 300 Vdcw and (C3-B) 200 μ F; 300 Vdcw RF P/N C-4958.

R58 to Resistor, Wire Wound; 440 ohms \pm 5%; 3W RF P/N R-3234.

Delete: C11, C56, C58, L4, and R17

Add: C84 Capacitor, Electrolytic; 5600 μ F; 20Vdcw RF P/N C-4959.

C85 Capacitor, Electrolytic; 5600 μ F; 20Vdcw RF P/N C-4959

R59 Resistor, Wirewound; 1 ohm \pm 5%; 3W RF P/N R-3221.

Page 8-33/8-34, Schematic Diagram, Main Frame Assembly.....

Change: C3-C to C84 (5600 μ F; 20V) and C3-D to C85 (5600 μ F 20V). See diagram.

Delete: C2, C11, C56, C58, and R17

L4-A, L4-B, and L4-C and show R58 removed from transformer T1 (terminal 16 and ground) and reconnected in place of L4-C (positive terminal of C3-A to positive terminal of C3-B). Change value of R58 to 440 ohms 3W.



RF COMMUNICATIONS, INC.
1680 UNIVERSITY AVENUE
ROCHESTER, NEW YORK, 14610, U.S.A.

INSTRUCTION MANUAL ADDENDUM


ADDENDUM No. PM-098D

APPLICABLE SDN No.(S) LPES-68

APPLICABLE DCN No.(S) LPR-233

APPLICABLE TO: RF-301/A
(MAIN FRAME ASSEMBLY)

Add: Resistor R59 (1 ohm; 3W) as shown in diagram below:





RF COMMUNICATIONS, INC.
1680 UNIVERSITY AVENUE
ROCHESTER, NEW YORK, 14610, U.S.A.

INSTRUCTION MANUAL ADDENDUM

ADDENDUM No. PM-0981

APPLICABLE TO: RF-301/A

APPLICABLE SDN No.(S) LPES-68

(162-0500 Assembly)

APPLICABLE DCN No.(S) LPE-234

The value of capacitor C15 on the 455 kHz Error Mixer Assembly (162-0500) is being selected during final test. One of the following sizes will be used:

<u>Size</u>	<u>RF P/N</u>
5pF	C-0103
10pF	C-0104
12pF	C-0105
15pF	C-0106
20pF	C-0108
24pF	C-0110

Change the parts list in your instruction manual PM-0301G or PM-0348G (page 7-6) to reflect the value of the capacitor that is installed in your unit. Refer to figure 8.7 for location of C15 on the assembly.



RF COMMUNICATIONS, INC.
1680 UNIVERSITY AVENUE
ROCHESTER, NEW YORK, 14610, U.S.A.

INSTRUCTION MANUAL ADDENDUM

ADDENDUM No. PM-0982

APPLICABLE SDN No.(S)

APPLICABLE DCN No.(S) LPE-239

APPLICABLE TO: RF-301/A

(162-0700 Assembly)

Make the following changes in your Instruction Manual PM-0301G or PM-0348G.

Page 7-8, Parts List, 162-0700.....

Change: Q4, Q5, Q7, and Q8 to Transistor, type
2N4916 RF P/N Q-0360.

R19, R27, and R42 to Resistor, 1K \pm 10%;1/4W
RF P/N R-0024.

R45 to Resistor; 390 ohms \pm 10%;1/4W RF P/N
R-0019.

Page 8-13/8-14, Schematic Diagram, 162-0700.....

Change: Q4, Q5, Q7, Q8, to 2N4916

R19, R27, and R42 to 1K

R45 to 390 ohms.



RF COMMUNICATIONS, INC.
1680 UNIVERSITY AVENUE
ROCHESTER, NEW YORK, 14610, U.S.A.

INSTRUCTION MANUAL ADDENDUM

ADDENDUM No. PM-0987

APPLICABLE SDN No.(S)

APPLICABLE DCN No.(S) LPE-241

APPLICABLE TO: RF-301/A

(162-0400 Assembly)

Make the following changes in your Instruction Manual
PM-0301G or PM-0348G.

Page 7-5, Parts List, 162-0400.....

Change: C25 to 43 pF \pm 2% RF P/N C-2469
 C9 to 110 pF RF P/N C-0127
 CR1, CR2, CR3, and CR4 to Diode Type 1N4454
 RF P/N CR-0705.

Page 8-7/8-8, Figure 8.6 Schematic Diagram, 162-0400.....

Change: C9 to 110 pF
 C25 to 43 pF
 CR1, CR2, CR3, and CR4 to 1N4454



RF COMMUNICATIONS, INC.
1680 UNIVERSITY AVENUE
ROCHESTER, NEW YORK, 14610, U.S.A.

INSTRUCTION MANUAL ADDENDUM

ADDENDUM No. PM-0989

APPLICABLE TO: RF-301/A

APPLICABLE SDN No.(S) LPES-73

(162-0500 Assembly)

APPLICABLE DCN No.(S)

Capacitor C24 has been removed from ground and reconnected across resistor R18 (B+ to emitter of Q2). Make the following changes in your instruction manual PM-0301G or PM-0348G.

Page 8-9/8-10, Circuit Diagram, 162-0500.....

Show C24 disconnected from ground and reconnected across R18.



RF COMMUNICATIONS, INC.
1680 UNIVERSITY AVENUE
ROCHESTER, NEW YORK, 14610, U.S.A.

INSTRUCTION MANUAL ADDENDUM

ADDENDUM No. PM-1029

APPLICABLE SDN No.(S) LPE-271

APPLICABLE DCN No.(S)

APPLICABLE TO: RF-301/A/P
(162-0800 Assembly)

Make the following changes in your Instruction Manual
PM-0301G, PM-0348G, or PM-0540A.

Page 7-9, Parts List, 162-0800 Assy.....

Change C59 to 91 pF, RF P/N C-2478

Page 8-15/8-16, Schematic Diagram, 162-0800 Assy.....

Change C59 to 91 pF.



RF COMMUNICATIONS, INC.
1680 UNIVERSITY AVENUE
ROCHESTER, NEW YORK, 14610, U.S.A.

INSTRUCTION MANUAL ADDENDUM

ADDENDUM No. PM-0984

APPLICABLE SDN No.(S) LPES-71

APPLICABLE DCN No.(S)

APPLICABLE TO: RF-301/A

(MAIN FRAME ASSEMBLY)

Make the following changes in your Instruction Manual PM-0301G or PM-0348G.

Page 8-33/8-34, Main Frame Assembly Schematic Diagram..

Add Ferrite Bead L-0184 in series from the wire connecting C56 (positive terminal) to pin 14 of K3.