




ILLUSTRATION BOOKLET


Part of 595-2980

PARTS PICTORIAL




Model HD-1418


Copyright © 1983
 Heath Company
 All Rights Reserved
 Printed in the United States of America




PICTORIAL 1-1




PICTORIAL 1-2




PICTORIAL 1-3




PICTORIAL 1-4




PICTORIAL 1-5




PICTORIAL 1-6




PICTORIAL 1-7




PICTORIAL 1-8




PICTORIAL 2-1



PICTORIAL 4-1



PICTORIAL 4-2




POSITION "A": CONTROL TURNED CCW
POSITION "B": CONTROL CENTERED
POSITION "C": CONTROL TURNED CW

PICTORIAL 5-1

CIRCUIT BOARD X-RAY VIEW

NOTE: To find the PART NUMBER of a component for the purpose of ordering a replacement part:

- A. Find the circuit board number (R5, C3, etc.) on the X-Ray View.
- B. Locate this same number in the "Circuit Component Number" column of the "Parts List."
- C. Adjacent to the circuit component number, you will find the PART NUMBER and DESCRIPTION which must be supplied when you order a replacement part.



(Shown from the component side.
The foil on the component side is shown in red.)