



Errata

The following section is a correction to the HF SSB transceiver reference manual, Codan part number 15-04076 Issue 1, 1997.

Antenna band or channel control

The following correction is in Chapter 9, *Link Setup mode—Antenna band or channel control*. The bandset values have been corrected to the values in the following table.

Outputs 4 2 1	Bandset 1 frequency ranges (MHz)	Bandset 2 frequency ranges (MHz)
L L L		< 2
L L H	< 2	2–2.99999
L H L	2–2.99999	3–3.99999
L H H	3–4.99999	4–5.99999
H L L	5–7.99999	6–8.99999
H L H	8–12.99999	9–12.99999
H H L	13–19.99999	13–19.99999
H H H	20–30	20–30

