


LADĚNÍ  
1. STUPNĚ  
BMP-3




6-Š1

BLOKOVÁNÍ	1
BLOKOVÁNÍ	2
~6,3V	3
-100V	4
~12,6V	5
~12,6V	6
~12,6V	7
~12,6V	8
KOSTRA	9
KOSTRA	10
KOSTRA	11
KOSTRA	12
-3000V	13
+350V	15
+225V	16
+3000V	17

ADĚNÍ  
STUPNĚ  
BMP-3

LADĚNÍ  
2. STUPNĚ  
BMP-3

VAZBA  
S AD  
BMP-1



Obr. 9. Schéma zapojení koncového stupně

LV-6 (R-137)

