



Inch - Fraction - Decimal - mm Conversion Chart

Inches			Decimal	mm
		1/64	0.0156	0.3969
	1/32		0.0313	0.7938
		3/64	0.0469	1.1906
1/16			0.0625	1.5875
		5/64	0.0781	1.9844
	3/32		0.0938	2.3813
		7/64	0.1094	2.7781
1/8			0.1250	3.1750
		9/64	0.1406	3.5719
	5/32		0.1563	3.9688
		11/64	0.1719	4.3656
3/16			0.1875	4.7625
		13/64	0.2031	5.1594
	7/32		0.2188	5.5563
		15/64	0.2344	5.9531
1/4			0.2500	6.3500
		17/64	0.2656	6.7469
	9/32		0.2813	7.1438
		19/64	0.2969	7.5406
5/16			0.3125	7.9375
		21/64	0.3281	8.3344
	11/32		0.3438	8.7313
		23/64	0.3594	9.1281
3/8			0.3750	9.5250
		25/64	0.3906	9.9219
	13/32		0.4063	10.3188
		27/64	0.4219	10.7156
7/16			0.4375	11.1125
		29/64	0.4531	11.5094
	15/32		0.4688	11.9063
		31/64	0.4844	12.3031
1/2			0.5000	12.7000

Inches			Decimal	mm
		33/64	0.5156	13.0969
	17/32		0.5313	13.4938
		35/64	0.5469	13.8906
9/16			0.5625	14.2875
		37/64	0.5781	14.6844
	19/32		0.5938	15.0813
		39/64	0.6094	15.4781
5/8			0.6250	15.8750
		41/64	0.6406	16.2719
	21/32		0.6563	16.6688
		43/64	0.6719	17.0656
11/16			0.6875	17.4625
		45/64	0.7031	17.8594
	23/32		0.7188	18.2563
		47/64	0.7344	18.6531
3/4			0.7500	19.0500
		49/64	0.7656	19.4469
	25/32		0.7813	19.8438
		51/64	0.7969	20.2406
13/16			0.8125	20.6375
		53/64	0.8281	21.0344
	27/32		0.8438	21.4313
		55/64	0.8594	21.8281
7/8			0.8750	22.2250
		57/64	0.8906	22.6219
	29/32		0.9063	23.0188
		59/64	0.9219	23.4156
15/16			0.9375	23.8125
		61/64	0.9531	24.2094
	31/32		0.9688	24.6063
		63/64	0.9844	25.0031
1			1.0000	25.4000

©DX Engineering 2013

P.O. Box 1491 - Akron, OH 44309-1491 USA

Phone: 800-777-0703 - Tech Support and International: 330-572-3200

email: DXEngineering@DXEngineering.com