

The attached diagram shows how to modify the cathode current metering circuit of the TS-520S to allow measuring either individual cathode currents of each output tube, or the combined current as normal.

I used an available small three position slide switch, fitted conveniently in the lower left hand corner of the case.

